

BEST COPY

AVAILABLE

For all of these :

THRU OUT FOLDER

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No. 11005

RECEIVED FROM Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080003-0

DATE REC'D 1-23-57		P.O. NO.		VENDOR PACKING SLIP NO.	
CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER
322	000000	10025	0	0	00
OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.		S.O. NO.	
00	03				
CHARGE TO QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION			QUANTITY	
25	737458 SHIP MEMO 85234			ACCEPTED	REJECTED
				25V	
			REMARKS		
			W.F. Pender		

RECEIVED BY HMC-1069 2-1-57 INSPECTED BY DUSA DATE 1/25/57 REJECTS RETURNED ON SHIP MEMO NO.

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2561 E. COLORADO ST., PASADENA, CALIF.

No. 11006

DATE REC'D 1-23-57		P.O. NO.		VENDOR PACKING SLIP NO.	
CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER
322	731755				
OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.		S.O. NO.	
00					
CHARGE TO QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION			QUANTITY	
129	731755 MACH 2 PART			ACCEPTED	REJECTED
	122-000000-10042-0-00-00-03			100	29
			REMARKS		
			RGT 3608		
			W.F. Pender		

RECEIVED BY HMC-1069 2-1-57 INSPECTED BY DUSA DATE 1/24/57 REJECTS RETURNED ON SHIP MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080003-0